5219 N. Shirley St., #100 Tacoma, WA 98407 P: (253) 752-2185 F: (253) 752-7083 www.PointRuston.com



October 15, 2007

Mr. Kevin L. Rochlin Remedial Project Manager U.S. Environmental Protection Agency Region 10 1200 Sixth Avenue, ECL-111 Seattle, WA 98101

RE:

Monthly Report: No. 136, September 2007

Operable Unit No. 02

Asarco Tacoma Smelter Site

Dear Mr. Rochlin:

Point Ruston is submitting this monthly report per the requirements of paragraph 48 of the Consent Decree for the above referenced site. Point Ruston will continue to provide monthly reports to EPA for the site organized in the same manner as previous reports prepared by Asarco to follow item (a) through (g) of this paragraph.

If you have any questions, please call me.

Sincerely,

Sue O'Neill Site Manager

Attachment (2 copies)

cc:

Chung Ki Yee - Washington Department of Ecology

Evan Griffiths - CH2MHill (2 copies)

Richard Kauffman - ATSDR c/o U.S. EPA Region 10

Leslie Ann Rose - Citizens for a Healthy Bay

USEPA SF 1288310

Monthly Report No. 136, September 2007 Operable Unit 02 Asarco Tacoma Smelter Site

- A. Actions taken to achieve compliance with the Consent Decree during the previous month.
 - 1. A regular monthly design review meeting was not held in September.
 - 2. Amendments to Asarco's final Upland Remediation Design (September 2006) are being prepared consistent with the Second Amendment to the Consent Decree.
 - 3. Remedial Action activities continued.
- B. Summary of sampling, tests, and all other data received or generated by Point Ruston in the previous month.
 - 1. Outfall activities including the following:

Section 2.3 of the Final Statement of Work (SOW) for Remedial Design and Remedial Action – Exhibit F to the Second Amendment requires Point Ruston to continue outfall monitoring. Outfalls will be monitored to determine if the monthly average surface water outfall concentrations for arsenic, copper, and zinc exceed 0.5 ppm at the North and South site outfalls until they are abandoned.

Weekly composite samples will be collected at each outfall during the construction season. During the winter season, outfall samples will be collected every other month. Asarco began the following schedule in May of 2003 which Point Ruston will continue to implement: weekly composite samples will be collected from May-October, and in December, February, and April.

Monthly averages and individual results for samples collected by Point Ruston from August 27th through September 17th are attached. There was no exceedance of the interim discharge limits.

- 2. Point Ruston collects OCF leachate in a 5,000 gallon polyethylene tank for offsite shipment and disposal. LCRS and LDCRS volumes are monitored weekly in accordance with the draft OCF OMMP. LCRS volumes currently average approximately 209 gallons per day on the LCRS. Point Ruston shipped 4,450 gallons of leachate (4.9 ppm results attached) on September 11, 2007.
- 3. Point Ruston completed air monitoring at the perimeter of Stack Hill during stack base demo operations and final remediation grading. Results of samples collected from August 20th through September 25th are attached. There were no exceedances. Perimeter air sampling at Stack Hill was discontinued in September 2007 following remediation completion of the Stack Hill property in August 2007.

Monthly Report No. 136, September 2007 Operable Unit 02 Asarco Tacoma Smelter Site

- C. Work Plans and other deliverables completed and submitted during the previous month.
 - 1. No comments were received from EPA during the month of September.
 - 2. Remedial Action during September included the following tasks:
 - OCF construction activities:
 - ➤ Maintained leachate collection system and shipped leachate for offsite treatment as necessary to maintain adequate storage capacity in the temporary storage tank.
 - Stack Hill construction activities:
 - > Maintained erosion and surface water controls
 - ➤ Completed post-remediation sampling by lot and preparation of post-remediation maps Remediation of the Stack Hill property was completed in August 2007. Results of Stack Hill Lot Sampling and property maps were submitted to EPA on September 10, 2007.
 - > Completed perimeter air monitoring
 - Site Capping construction activities:
 - > Continued concrete sorting and sizing
 - > Placed residential soils and Stack Hill soils as subgrade
 - > Maintained erosion and surface water controls
 - Site-wide remediation activities:
 - > Continued surface water controls
 - > Maintained haul roads and stockpiles onsite
- D. Actions scheduled for the next six weeks.
 - 1. Point Ruston anticipates receiving comments from EPA on the Construction Management Plan, Construction Quality Assurance Plan and Performance Standards Verification Plan submitted to EPA on June 22nd.
 - 2. The following Remedial Action tasks are planned to continue:
 - RA Monitoring:
 - > Outfall sampling (weekly composite samples) during scheduled months
 - OCF construction activities:
 - > Continue collection of leachate for offsite disposal
 - > Continue monitoring of leachate volumes
 - Stack Hill construction activities:
 - > Erosion controls and site maintenance
 - Site Capping construction activities:
 - > Concrete sorting and sizing.
 - Site-wide construction activities:
 - > Continue surface water controls
 - Maintain roads and stockpiles onsite

Monthly Report No. 136, September 2007 Operable Unit 02 Asarco Tacoma Smelter Site

- E. Percentage completion, unresolved delays encountered or anticipated that may affect schedule, and efforts to mitigate delays.
 - 1. Point Ruston Remediation Design is under revision based on comments from EPA.
- F. Modifications to work plans or schedules proposed to or approved by EPA.
 - 1. The Second Amendment to the Consent Decree was finalized and the sale of the property to Point Ruston LLC completed on October 31, 2006.
- G. Activities undertaken to support Community Relations Plan during the previous month and planned for the next four weeks.
 - 1. Point Ruston attends the Town of Ruston's Town Council meetings routinely to answer question or give briefings regarding the status of RA and development planning activities (1st and 3rd Monday of each month).
 - 2. Point Ruston is working with the City of Tacoma on development plans which incorporate remediation components for the site.
 - 3. Point Ruston is working with MetroParks to incorporate the capping component into the Peninsula Park design.
 - 4. Point Ruston meets with the Town of Ruston, City of Tacoma and MetroParks to address operation, maintenance, and monitoring issues at the site.

Table 1. Summary of September 2007 Outfall Data for As, Cu, and Zn Compared to SOW Limit

Location	As Conc. ppm	% of SOW Limit*	Cu Conc. ppm	% of SOW Limit*	Zn Conc. ppm	% of SOW Limit*
South Outfall	0.000	0.00%	0.008	1.50%	0.005	1.00%
North Outfall	0.000	0.00%	0.000	0.00%	0.000	0.00%

 $^{^{\}star}$ 0.5 ppm is the limit of As, Cu, and Zn allowed as documented in the SOW. Non-detect = 0.000

Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-001

Client Sample ID: TSM0807427

Report Date: 09/26/07

Collection Date: 08/27/07 15:10

DateReceived: 09/19/07

Analyses	Result Ui	nits Q	ualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND mg	/L		0.1		E200.7	09/20/07 21:45 / rlh
Copper	ND mg	/L		0.01		E200.7	09/20/07 21:45 / rlh
Zinc	ND mg	/L		0.01		E200.7	09/20/07 21:45 / rlh



Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-002

Client Sample ID: TSM0807127

Report Date: 09/26/07

Collection Date: 08/27/07 15:20

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL				•			
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:14 / rlh
Copper	ND	mg/L		0.01		E200.7	09/21/07 10:14 / rlh
Zinc	ND	mg/L		0.01		E200.7	09/21/07 10:14 / rlh



Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-003

Client Sample ID: TSM0907404

Report Date: 09/26/07

Collection Date: 09/04/07 10:45

DateReceived: 09/19/07

Analyses	Result U	nits (Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND mg	g/L		0.1		E200.7	09/21/07 10:17 / rlh
Copper	ND mg	g/L		0.01		E200.7	09/21/07 10:17 / rlh
Zinc	ND mg	g/Ĺ		0.01		E200.7	09/21/07 10:17 / rlh

Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-004

Client Sample ID: TSM0907104

Report Date: 09/26/07

Collection Date: 09/04/07 10:53

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:21 / rlh
Copper	ND	mg/L	(0.01		E200.7	09/21/07 10:21 / rlh
Zinc	. ND	mg/L	(0.01		E200.7	09/21/07 10:21 / rlh



Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-005

Client Sample ID: TSM0907410

Report Date: 09/26/07

Collection Date: 09/10/07 09:10

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:25 / rlh
Copper	0.02	mg/L		0.01		E200.7	09/21/07 10:25 / rlh
Zinc	0.01	mg/L		0.01		E200.7	09/21/07 10:25 / rlh

Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-006

Client Sample ID: TSM0907110

Report Date: 09/26/07

Collection Date: 09/10/07 09:15

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:28 / rlh
Copper	0.02	mg/L		0.01		E200.7	09/21/07 10:28 / rlh
Zinc	0.01	mg/L		0.01		E200.7	09/21/07 10:28 / rlh



Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-007

Client Sample ID: TSM0907417

Report Date: 09/26/07

Collection Date: 09/17/07 09:45

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL							
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:39 / rlh
Copper	ND	mg/L		0.01		E200.7	09/21/07 10:39 / rlh
Zinc	ND	mg/L		0.01		E200.7	09/21/07 10:39 / rlh



Client:

Point Ruston LLC

Project:

Tacoma Smelter Outfall Monitoring

Lab ID:

B07091643-008

Client Sample ID: TSM0907117

Report Date: 09/26/07

Collection Date: 09/17/07 10:00

DateReceived: 09/19/07

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL	THE SECTION OF SECTION						
Arsenic	ND	mg/L		0.1		E200.7	09/21/07 10:50 / rlh
Copper	. 0.01	mg/L		0.01		E200.7	09/21/07 10:50 / rlh
Zinc	0.01	mg/L		0.01		E200.7	09/21/07 10:50 / rlh

Client:

Point Ruston LLC

Project:

Tacoma Smelter OCF Leachate

Lab ID:

B07090372-001

Client Sample ID: TSM090704

Report Date: 09/07/07

Collection Date: 09/04/07 10:20

DateReceived: 09/06/07

Matrix: Aqueous

Analyses	Result	Units	Qualifiers	RL	MCL/ QCL	Method	Analysis Date / By
METALS, TOTAL Arsenic	4.9	mg/L		0.1		E200.7	09/07/07 14:07 / jjw

Report

RL - Analyte reporting limit.

Definitions: QCL - Quality control limit.

MCL - Maximum contaminant level.

ND - Not detected at the reporting limit.

SPECTRA Laboratories

2221 Ross Way • Tacoma, WA 98421 • (253) 272-4850 • Fax (253) 572-9838 • www.spectra-lab.com

09/14/2007

Point Ruston 5219 N. Shirley St., Suite 100 Tacoma, WA 98407

Project:

Stack Hill/Air Monitoring

Date Received: Spectra Project: 2007090119

09/10/2007

							Date
Client ID	Spectra #	Analyte	Result	Units	Method	<u>Matrix</u>	Sampled
082007-181	1	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/20/2007
082007-719	2	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/20/2007
082007-333	3	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/20/2007
082407-181	4	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/24/2007
082407-719	5	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/24/2007
082407-333	6	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/24/2007
082707-181	7	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/27/2007
082707-179	8	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/27/2007
082707-333	9	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	08/27/2007
090707-181	10	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	09/07/2007
090707-719	. 11	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	09/07/2007
090707-333	12	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	09/07/2007

SPECTRA LABORATORIES

Steve Hibbs, Laboratory Manager a8/scj

Page 1 of 1

SPECTRA Laboratories

2221 Ross Way • Tacoma, WA 98421 • (253) 272-4850 • Fax (253) 572-9838 • www.spectra-lab.com

SEP 2 4 2007

09/20/2007

Point Ruston 5219 N. Shirley St., Suite 100 Tacoma, WA 98407

Project:

Air Monitoring/Stack Hill

Date Received:

09/17/2007

Spectra Project:

2007090251

							Date
Client ID	Spectra #	Analyte	Result	<u>Units</u>	Method	Matrix Sa	ampled
091007-719	1	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	10/2007
091007-181	2	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	10/2007
091007-333	3	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	10/2007
091107-181	4	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	1/2007
091107-719	5	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	1/2007
091107-333	6	Arsenic	< 0.1	μg/m3	SW846 7060A	· Air Cassette 09/	1/2007
091207-333	7	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	12/2007
091207-181	. 8	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	12/2007
091207-719	9	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	12/2007
091307-123	10	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	3/2007
091307-719	11	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/1	3/2007
091307-646	12	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	3/2007
091407-719	13	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/	4/2007
091407-123	14	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/1	4/2007

SPECTRA LABORATORIES

Steve Hibbs, Laboratory Manager a8/scj

Page 1 of 2

SPECTRA Laboratories

222 i Ross Way • Tacoma, WA 98421 • (253) 272-4850 • Fax (253) 572-9838 • www.spectra-lab.com

09/20/2007

Point Ruston 5219 N. Shirley St., Suite 100 Tacoma, WA 98407

Project:

Air Monitoring/Stack Hill

Date Received:

09/17/2007

Spectra Project:

2007090251

Client ID	Spectra #	Analyte	Result	<u>Units</u>	Method	<u>Matrix</u>	Date <u>Sampled</u>
091407-181	15	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette	09/14/2007

SPECTRA LABORATORIES

Steve Hibbs, Laboratory Manager

a8/scj

2221 Ross Way • Tacoma, WA 98421 • (253) 272-4850 • Fax (253) 572-9838 • www.spectra-lab.com

10/11/2007

Point Ruston 5219 N. Shirley St., Suite 100 Tacoma, WA 98407

Project:

Stack Hill/Air Monitoring

Date Received:

10/01/2007

Spectra Project: 2007100024

Client ID	Spectra#	Analyte	Result	Units	Method	Date <u>Matrix</u> Sampled	
091907-646	l specua #	Analyte	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/19/2007	
091907-719	2	Arsenic	< 0.1	µg/m3	SW846 7060A	Air Cassette 09/19/2007	
091907-123	3	Arsenic	< 0.1	μ g/m 3	SW846 7060A	Air Cassette 09/19/2007	
092007-181	4 .	Arsenic	< 0 .1	µg/m3	SW846 7060A	Air Cassette 09/20/2007	
092007-646	5	Агзеліс	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/20/2007	
092007-123	6	Arsenic	< 0.1	μ g/m 3	SW846-7060A	Air Cassette 09/20/2007	
092107-123	7	Arsenic	< 0.1	µg/m3	SW846 7060A	Air Cassette 09/21/2007	
092107-719	8	Arsenic	< 0.1	µg/m3	SW846 7060A	Air Cassette 09/21/2007	
092107-181	9	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/21/2007	
092407-333	10	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/24/2007	
092407-646	11 -	Arsenic	< 0.1	μ g/m3	SW846 7060A	Air Cassette 09/24/2007	
092407-181	12	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/24/2007	
092507-646	13	Arsenic	< 0.1	μg/m3	SW846 7060A	Air Cassette 09/25/2007	
092507-123	14	Arsenic	< 0, t	μg/m3	SW846 7060A	Air Cassette 09/25/2007	

SPECTRA LABORATORIES

Steve Hibbs, Laboratory Manager

From: SPECTRA LABS



2221 Ross Way • Tacoma, WA 98421 • (253) 272-4850 • Fax (253) 572-9838 • www.spectra-lab.com

10/11/2007

Point Ruston 5219 N. Shirley St., Suite 100 Tacoma, WA 98407

Project:

Stack Hill/Air Monitoring

Date Received:

10/01/2007

Spectra Project: 2007100024

Client ID	Spectra #	Analyte	Result	Units	Method	Matrix	Date Sampled
092507-719	. 15	Arsenic	< 0.1	μ g/m 3	SW846 7060A	Air Cassette	09/25/2007

SPECTRA LABORATORIES

Steve Hibbs, Laboratory Manager